



**Roofing Plus**  
1525 University Drive  
Auburn, GA 30011  
7704641030

# Work Completed

**Check In/Out With:** Steve

**Invoice #**  
**Invoice Date**

**149221861**  
**04/04/24**

## Rust stain on wall (Emergency)

1.00

### Description:

There is rust on the wall around steel plate at the breeze way.

### Work Completed:

Investigate source of water getting into the wall. Tech found damage to the concrete joint at the entrance to the breezeway allowing water inside the wall. This water is exiting the wall at the steel wall plate causing the rust stains. Tech cleaned out the damaged joint and filled with caulking. This is a temporary repair to stop the water intrusion and should be further investigated by and structural engineer and permanently repaired.

### Before:



### After:

