## **Management Report 04.19.24**

- Diamond Landscape Management Foliage construction project ongoing with some dead shrubs to still be replaced on the Tower 2 pool deck. New sod has been laid down in various areas around Tower 1 and Tower 2. The irrigation timer was struck by lightning with a recent storm and surged. It was replaced Tuesday 04/16/24 with the timer set for 1 hour runs twice a day for the new sod. Bi-Annuals for the middle walkway area of Tower 1 beachside, marquee sign area near Tower 2 and Tower 2 pool deck will be installed over the coming weeks and pine straw laid down for the property. Inquiries are also being made for scheduling of the 1<sup>st</sup> of 2 palm tree prunings for the year.
- Ongoing Oracle elevator repairs- Tower 2 elevator #2 is out of service until the belts can be replaced as noted on the annual elevator inspection report. This will be discussed further as part of New Business for the Board meeting on 04.19.24.
- **Florida Power & Light/Mastec** Production is still in process for the additional 33 foot black tapered LED lights that will go in areas surrounding Tower 2 and in the back lot.
- Tower 1 & 2 bollards Tower 2 traffic bollards are still in process with 1 left to sand and paint on P2. This was slowed by the Valcourt project. Tower 1 black light bollards are also being

- sanded and painted with the remaining ones left located inside the pool area.
- Hiller Continuation of the Semi-annual and quarterly fire alarm and sprinkler inspections were postponed by Hiller until 04.29.24. The Association is waiting for repairs to be scheduled from the annual unit sprinkler inspections conducted in October 2023. The repairs will be noticed at a minimum 1 month to Owners as entry to affected units will be needed and each tower's repairs will take roughly 1 week.
- Roofing Plus Rust leak was observed below the crossover bridge at Tower 2. Roofing Plus re-inspected the area and has determined it to not be under warranty as part of the original contract. A temporary repair was completed by Roofing Plus with the recommendation of an engineer consultant for further evaluation. The Association is in the process of obtaining bids for surveys.
- Marquee Sign repair Triple H completed a repair to the marquee sign that was damaged by an impaired driver on 03.01.24. The affected area of the sign will be painted by the Association maintenance team.
- BE-CI Exterior Condition Survey for Tower 1 stacks 1 & 9 and Tower 2 stacks 7 & 8 Tentatively May 9