



4325 Lafayette Street, Suite A
 Marianna, FL 32446
 Office: (850) 482-7366
 centuryfp.com

Annual Extinguisher Inspection
 Inspected and tested per NFPA 10

Inspected Site
 Grand Panama Tower #1
 11807 Front Beach Road
 Panama City Beach, FL 32407
 Date/Time: 01/26/2026 08:17
 Inspection Reference #: 44432894
 Conducted by: Jeff Searles
 Permit #:

Prepared For
 Grand Panama
 11807 Front Beach Road
 Panama City Beach, FL 32407

Inspection and Testing Summary

Device Description	Total Devices	Number Inspected/Tested	Number Passed	Number Needing Service
Fire Extinguishers	77	77	8	69



Inspection Site
 Grand Panama Tower #1
 11807 Front Beach Road

Customer
 Grand Panama
 11800 Front Beach Road

Conducted by: Jeff Searles

Fire Extinguisher Inspection | null

Unit	Loc	Manuf.	Manuf. Date	Size	Type	Model	Serial	Due Dates		Additional Services Due						
								Next Service Type	Next Service Year	Rechg	Cabinet	Hose	Gauge	Weight	Accessible	Notes
Ground floor	West	Amerex	2001	10 lb	ABC		sg788716	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign & sticker arrow
Ground Floor	Pool equipment room	Amerex	2013	6 L	Water		A0331902	6 Year	2028	Pass	Pass	Pass	Pass	Pass	Yes	
Ground floor	West across pool equip. Rm	1st Alert	2023	2.5 lb	ABC		I06071952	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	
Ground floor	West rear	Amerex	2007	10 lb	ABC		ZA790528	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 and sticker arrow signs
Ground floor	Mid	Amerex	2011	10 lb	ABC		AP922280	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Arrow sticker
Ground floor	East by stairwell	Amerex	2019	10 lb	ABC		F63766478	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 & sticker arrow sign
1st floor	FACP room	Amerex	2023	10 lb	ABC		I02231998	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
1st floor	Pump room	Amerex	2023	10 lb	ABC			6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Recommend add 10lb abc Recommend 10lb abc for pump room Needs metal 90 degree sign Missing Extinguisher
1st floor	Pump room	Amerex	2024	5 lb	ABC		I16376628	6 Year	2030	Pass	Pass	Pass	Pass	Pass	Yes	
1st floor	Elevator lobby	Amerex	2020	10 lb	ABC		00	6 Year	2026	Pass	Pass	Pass	Pass	Pass	Yes	6yr due Needs metal 90 degree sign
1st floor	West	Amerex	2023	10 lb	ABC		xu245479	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
1st floor	Trash room	Amerex	2025	10 lb	ABC		I53929950	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs extinguisher inside sign Mounting bracket hook
2nd floor	East	Amerex	2023	10 lb	ABC		I02284252	6 Year	2029	Pass	Needs Service	Pass	Pass	Pass	Yes	Needs metal 90 degree sign Needs cabinet glass
2nd floor	Elevator lobby	Amerex	2025	10 lb	ABC		I539930413	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
2nd floor	West	Amerex	1994	10 lb	ABC		LZ598408	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
3rd floor	West	Amerex	2025	10 lb	ABC		I53895971	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
3rd floor	Elevator lobby	Amerex	2010	10 lb	ABC		S379900	6 Year	2028	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
3rd floor	East	Amerex	2013	10 lb	ABC		BX119165	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
4th floor	West	Amerex	2007	10 lb	ABC		yp209845	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign



Inspection Site
 Grand Panama Tower #1
 11807 Front Beach Road

Customer
 Grand Panama
 11800 Front Beach Road

Conducted by: Jeff Searles

Fire Extinguisher Inspection | null

Unit	Loc	Manuf.	Manuf. Date	Size	Type	Model	Serial	Due Dates		Additional Services Due						
								Next Service Type	Next Service Year	Rechg	Cabinet	Hose	Gauge	Weight	Accessible	Notes
4th floor	East	Badger	2007	10 lb	ABC		YP209868	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
4th floor	Elevator lobby	Badger	2007	10 lb	ABC		yp209839	Hydro	2031	Pass	Needs Service	Pass	Pass	Pass	Yes	Needs metal 90 degree sign Cabinet door is broken
5th floor	West	Amerex	2019	10 lb	ABC		F70113157	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
5th floor	Elevator lobby	Amerex	2021	10 lb	ABC		G98142756	6 Year	2027	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
5th floor	East	Amerex	2017	10 lb	ABC		c99209952	Hydro	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
6th floor	East	Amerex	2005	10 lb	ABC		xe979911	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
6th floor	Elevator lobby	Amerex	2001	10 lb	ABC		sn020830	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
6th floor	West	Amerex	2025	10 lb	ABC		I53929946	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
7th floor	East	Amerex	2019	10 lb	ABC		f59235570	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
7th floor	Elevator	Amerex	2007	10 lb	ABC		ZA797620	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
7th floor	West	Amerex	2025	10 lb	ABC		i53895969	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
8th floor	East	Amerex	2001	10 lb	ABC		sn022019	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
8th floor	West	Amerex	2023	10 lb	ABC		00	6 Year	2029	Needs Service	Pass	Pass	Pass	Pass	Yes	Needs recharge Needs metal 90 degree Need recharge
8th floor	Elevator lobby	Amerex	2025	10 lb	ABC		i53949244	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
9th floor	East	Amerex	2001	10 lb	ABC		sn045409	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
9th floor	Elevator lobby	Amerex	2025	10 lb	ABC		I53930415	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
9th floor	West	Amerex	2025	10 lb	ABC		I53944460	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
10th floor	West	Amerex	2025	10 lb	ABC		i53944443	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
10th floor	Elevator lobby	Amerex	2017	10 lb	ABC		c96080376	Hydro	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
10th floor	East	Amerex	2001	10 lb	ABC		sm984823	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
1st floor	East	Amerex	2023	10 lb	ABC		yp209803	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 sign



Inspection Site
 Grand Panama Tower #1
 11807 Front Beach Road

Customer
 Grand Panama
 11800 Front Beach Road

Conducted by: Jeff Searles

Fire Extinguisher Inspection | null

Unit	Loc	Manuf.	Manuf. Date	Size	Type	Model	Serial	Due Dates		Additional Services Due						
								Next Service Type	Next Service Year	Rechg	Cabinet	Hose	Gauge	Weight	Accessible	Notes
11th floor	West	Badger	2007	10 lb	ABC		yp209798	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
11th floor	Elevator lobby	Amerex	2007	10 lb	ABC		yp209802	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
11th floor	East	Amerex	2025	10 lb	ABC		I53895968	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
12th floor	East	Amerex	2007	10 lb	ABC		yp209871	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
12th floor	Elevator lobby	Amerex	2019	10 lb	ABC		yp209797	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
12th floor	West	Amerex	2006	10 lb	ABC		yd348934	Hydro	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
13th floor	West	Amerex	2024	10 lb	ABC		i23118891	6 Year	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
13th floor	Elevator lobby	Amerex	2025	10 lb	ABC		i53895976	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
13th floor	East	Amerex	2024	10 lb	ABC		I17899379	6 Year	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
14th floor	East	Amerex	2023	10 lb	ABC		00	6 Year	2026	Pass	Pass	Pass	Pass	Pass	Yes	Due for 6 yr Needs metal 90 degree sign
14th floor	East	Amerex	2021	10 lb	ABC		g16881199	6 Year	2027	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
14th floor	Elevator lobby	Amerex	2019	10 lb	ABC		i59234881	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
15th floor	East	Amerex	2011	10 lb	ABC		ad726863	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
15th floor	Elevator	Amerex	2006	10 lb	ABC		xy404355	Hydro	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
15th floor	West	Amerex	2010	10 lb	ABC		x771783	6 Year	2028	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
16th floor	West	Amerex	2025	10 lb	ABC		i53929947	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
16th floor	Elevator lobby	Amerex	2023	10 lb	ABC		I17781611	6 Year	2029	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
16th floor	East	Badger	2006	10 lb	ABC		x993950	6 Year	2031	Pass	Pass	Needs Service	Pass	Pass	Yes	Needs metal 90 degree sign Needs hose strap
17th floor	East	Amerex	2015	10 lb	ABC		b04742341	Hydro	2028	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
17th floor	Elevator lobby	Amerex	2023	10 lb	ABC		00	6 Year	2029	Needs Service	Pass	Pass	Pass	Pass	Yes	Recharge Needs metal 90 degree sign Recharge
17th floor	Elevator lobby	Amerex	2006	10 lb	ABC		xy402030	Hydro	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign



Inspection Site
 Grand Panama Tower #1
 11807 Front Beach Road

Customer
 Grand Panama
 11800 Front Beach Road

Conducted by: Jeff Searles

Fire Extinguisher Inspection | null

Unit	Loc	Manuf.	Manuf. Date	Size	Type	Model	Serial	Due Dates		Additional Services Due						
								Next Service Type	Next Service Year	Rechg	Cabinet	Hose	Gauge	Weight	Accessible	Notes
18th floor	East	Amerex	2016	10 lb	ABC		b72616293	Hydro	2028	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
18th floor	Elevator lobby	Amerex	2024	10 lb	ABC		i31920996	6 Year	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
18th floor	West	Amerex	2021	10 lb	ABC		g98143073	6 Year	2027	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
19th floor	Elevator lobby	Amerex	2024	10 lb	ABC		i31917500	6 Year	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
19th floor	East	Amerex	1995	10 lb	ABC		mr919534	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
19th floor	West	Amerex	2021	10 lb	ABC		g98190203	6 Year	2027	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
20th floor	East stairs	Amerex	2019	10 lb	ABC		f62650465	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
20th floor	West stairs	Amerex	2016	10 lb	ABC		b72616842	Hydro	2030	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
20th floor	Elevator lobby	Amerex	2025	10 lb	ABC		i53930422	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Need metal 90 degree sign
21st floor	West stairs	Amerex	2019	10 lb	ABC		f70342025	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Needs metal 90 degree sign
21st floor	East stairs	Amerex	2018	10 lb	ABC		e94106004	Hydro	2030	Pass	Pass	Pass	Pass	Pass	Yes	Need metal 90 degree sign
21st floor	Elevator lobby	Amerex	2023	10 lb	ABC		00	6 Year	2026	Needs Service	Pass	Pass	Pass	Pass	Yes	Hydro Recharge
22nd floor	West stairs	Amerex	2021	10 lb	ABC		g98113823	6 Year	2027	Pass	Pass	Pass	Pass	Pass	Yes	Need metal 90 degree sign
22nd floor	Elevator lobby	Amerex	2001	10 lb	ABC		sn017824	6 Year	2031	Pass	Pass	Pass	Pass	Pass	Yes	Need metal 90 degree sign
22nd floor	East stairs	Amerex	2007	10 lb	ABC		f228388	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	Need metal 90 degree sign
22nd floor	Elevator equip rm	Amerex	2007	10 lb	ABC		ys275707	Hydro	2031	Pass	Pass	Pass	Pass	Pass	Yes	



Inspection Site
 Grand Panama Tower #1
 11807 Front Beach Road

Customer
 Grand Panama
 11800 Front Beach Road

Conducted by: Jeff Searles

Deficiencies with Comments

Fire Extinguishers (Building)		2214516889888641	
Suite/Unit	System Type/Name	Deficiency	Comments
Ground floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
Ground floor	Location: West rear Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
Ground floor	Location: East by stairwell Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
1st floor	Location: FACP room Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
1st floor	Location: Pump room Type: ABC Size: 10 lb	Additional Services: <i>Extinguisher is missing.</i>	Recommend 10lb abc for pump room
1st floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>Extinguisher is due for 6 Year</i>	No Issue
1st floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
1st floor	Location: Trash room Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
2nd floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
2nd floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
2nd floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
3rd floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
3rd floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
3rd floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
4th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
4th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue

**Inspection Site**Grand Panama Tower #1
11807 Front Beach Road**Customer**Grand Panama
11800 Front Beach Road

Conducted by: Jeff Searles

Suite/Unit	System Type/Name	Deficiency	Comments
4th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
5th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
5th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
5th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
6th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
6th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
6th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
7th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
7th floor	Location: Elevator Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
7th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
8th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
8th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>Extinguisher Needs to be Reviewed</i>	Needs recharge
9th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
9th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
10th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
10th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
10th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue

**Inspection Site**Grand Panama Tower #1
11807 Front Beach Road**Customer**Grand Panama
11800 Front Beach Road

Conducted by: Jeff Searles

Suite/Unit	System Type/Name	Deficiency	Comments
1st floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
11th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
11th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
11th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
12th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
12th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
12th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
13th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
13th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
13th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
14th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>Extinguisher is due for 6 Year</i>	No Issue
14th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
14th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
15th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
15th floor	Location: Elevator Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
15th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
16th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue

**Inspection Site**Grand Panama Tower #1
11807 Front Beach Road**Customer**Grand Panama
11800 Front Beach Road

Conducted by: Jeff Searles

Suite/Unit	System Type/Name	Deficiency	Comments
16th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
17th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
17th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>Extinguisher Needs to be Reviewed</i>	Recharge
17th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
18th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
18th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
18th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
19th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
19th floor	Location: East Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
19th floor	Location: West Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
20th floor	Location: East stairs Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
20th floor	Location: West stairs Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
20th floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
21st floor	Location: West stairs Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
21st floor	Location: East stairs Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
21st floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>Extinguisher Needs to be Reviewed</i>	Hydro
22nd floor	Location: West stairs Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue



Inspection Site

Grand Panama Tower #1
11807 Front Beach Road

Customer

Grand Panama
11800 Front Beach Road

Conducted by: Jeff Searles

Suite/Unit	System Type/Name	Deficiency	Comments
22nd floor	Location: Elevator lobby Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue
22nd floor	Location: East stairs Type: ABC Size: 10 lb	Additional Services: <i>No Issue</i>	No Issue

Date: 01/26/2026 08:17



4325 Lafayette Street, Suite A
Marianna, FL 32446
Office: (850) 482-7366

Inspection Site

Grand Panama Tower #1
11807 Front Beach Road

Customer

Grand Panama
11800 Front Beach Road

Conducted by: Jeff Searles

Technician Signature:

A handwritten signature in black ink, appearing to be "Jeff Searles", written over a white background.

Statement

I state the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operation condition upon completion of this inspection except as noted.