

Irrigation Estimate for Repair(s)



Employee:	Preston peuhs
Date:	7/19/2023
Property:	Grand Panama Resort
Job Number:	89-20295-FL
Customer Reference #	0

Status of system Funtional

Status of system Funtional

Job Assignment and Tasks to be Completed

Mp need added back and nozzle and head replacement

Zone one needs wire replaced and 40 mp nozzles to be adjust to fit the two zones

Part Search - Description Term:

Not Found	Enter Search Term Above	0.00			
Part #	Item Description	Qty		Unit Price	Extended Price
MP200090	.4 in/hr precipitation rate, 13' to 21' radius, 90° to 210° adjustable arc	40	x	\$ 11.85 =	\$474.00
1806	1800 SPRAY HEAD, BODY ONLY, 6" POP-UP HEIGHT	5	x	\$ 11.75 =	\$58.75
10h	10' RADIUS, HALF CIRCLE PATTERN	10	x	\$ 1.70 =	\$17.00
WPSK20	ICE KIT SILICONE TUBE WITH RED/YELLOW TWIST-ON WIRE N	10	x	\$ 3.13 =	\$31.30
Vbstd	BODY & GREEN LID	1	x	\$ 70.45 =	\$70.45
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
	Not Found		x	0.00 =	\$0.00
MISC	2 inch ball valve with hose bib	1	x	\$ 50.00 =	\$50.00
MISC			x	0.00 =	\$0.00

Rental Equipment

Pro900	Wire Tracer / Valve Locator	0	x	Days	\$50.00 =	Rental Price
			x	Days	0.00 =	\$0.00

Price Estimates:

Tech:	8 hrs.	x	\$95.00 =	\$760.00
Laborer:	0 hrs.	x	\$55.00 =	\$0.00
Service Charge	0	x	\$95.00 =	\$0.00
Materials:			=	\$701.50
Misc Materials	0	x	\$0.00 =	\$0.00
Contract Material Adjustment	-1	x		\$0.00
Rental Equipment Cost:			=	\$0.00
Contract Labor Adjustment	-1	x	\$0.00	\$0.00
Total estimated Cost:			=	\$1,461.50

Notes:

Estimate valid for 30 days

Print Name NANCY STOUALL, ASSN Secretary Signature Nancy Stouall Date 07/19/23